PM BULLETIN

Max Speeds for M939s

It's official, drivers. Change 1 to TM 9-2320-272-10 sets maximum safe operating speeds for M939/A1/A2-series 5-ton trucks:

Highway and secondary roads 40 mph Cross country roads 35 mph Sand and snow 25 mph Icy conditions 12 mph

PLS Tail Lights

Need 12-volt light bulbs for the PLS's composite tail light? Don't use the ones shown as Items 7 and 8 in Fig 98 of TM 9-2320-364-24P—they're the wrong bulbs. Instead, use NSN 6240-00-143-3159 for Item 7 and NSN 6240-00-617-0991 for Item 8.

HMMWV Oil Pan Installation

Replacing a HMMWV oil pan is tough enough with all the parts you need on-hand. But Fig 4 of TM 9-2320-280-24P-1 makes no reference to nut, NSN 5310-01-158-6257, and two washers, NSN 5310-00-582-5965 (box of 100), needed to mount the starter cable support bracket. The nut and washers are found in Fig 66 as Items 34 and 35.

M35A3 Beadlock

Need only the beadlock for a wheel on the M35A3 2¹/2-ton truck? Make a note in Fig 117 of TM 9-2320-386-24P that Item 2 is NSN 2530-01-398-2022. You don't have to order the entire wheel to get the beadlock.

Elastic Cord for Covers

If your truck's cargo and cab covers are secured by black elastic ("bungee") cord, you can make your own replacements. Get 280 feet of bulk cord with NSN 4020-01-463-8181.

HEY! CHECK OUT THESE PM

TIPS FOR WHEELED

VEHICLES.

6K VRRT Forklift Clip

BOARD

The internal retainer clip for the spotlight assembly on the variable reach rough terrain forklift is now available separately. Order it with NSN 5340-00-693-4175 and make a note until the NSN is added to Fig 61 of TM 10-3930-660-24P.

HMMWV Transmission Filter

NSN 4330-01-438-3813 gets a transmission filter kit for M998A2-series, M1113 enhanced capacity vehicles (ECV) and M1114 up-armor HMMWVs. The kit includes a seal and filter. It doesn't include the reusable transmission oil pan gasket, NSN 5330-01-360-5271. The kit includes Items 35 and 36 in Fig 94 of TM 9-2320-280-24P or Items 12 and 13 in Fig 88, TM 9-2320-387-24P.

M1022A1 Dolly Set Seal

NSN 5330-01-464-9956 gets a seal for the wheel assembly on the M1022A1 dolly set. The entry for Item 13 in Fig 17 of TM 9-2330-390-14&P is wrong. The item is not a spacer.

HMMWV Wheel Kit

NSN 2530-01-443-3405 is the new kit NSN that gets Items 17-19 and 22-29 in Fig 139 of TM 9-2320-280-24P-1. The current NSN is wrong. Items 20 (runflat device for either a bias or radial tire) and 21 (lubricant for either a bias or radial tire) are not included in the kit. For a complete tire and wheel, see Fig 140.

M870A1 Hub Cover

NSN 5340-01-042-0573 gets the axle hub cover for the M870A1 40-ton semitrailer. The cover's vent plug also comes with this NSN even though it's not shown with Item 2 of Fig 20 in TM 5-2330-378-14&P.

HMMWV Brush Guard Kits

M998A2-series HMMWVs have their own brush guard kits, NSN 2510-01-461-7075. The kit shown in Fig 400 of TM 9-2320-280-24P-2, NSN 2590-01-328-2904, is only for basic and M998A1-series HMMWVs. Make a note until the TM catches up with this information.

WE'RE TRUCKING NOW!

FFB 00

1